TypeL #Hits Search Text	#Hits Search	Hits Search	Search	ct.	DBs	Time Stamp	StampComments	Error Definition	Errors
toilet near5 BRS L1 364 (automatic adj5 flush\$3)	toilet near5 364 (automatic adj flush\$3)	toilet near5 64 (automatic adj flush\$3)	lear5 ic adj		USPAT; US-PGPUB; 20 EPO; JPO; 14 DERWENT	2004/10/25 14:45			0
BRS L2 385 (automatic adj5 flush\$3)	toilet near8 385 (automatic adj flush\$3)	toilet near8 (automatic adj flush\$3)	lear8 ic adj		USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/25			0
BRS L3 395 (automatic adj5 flush\$3)	toilet near10 395 (automatic adj flush\$3)	toilet near10 95 (automatic adj flush\$3)	near10 ic adj		USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/25 14:45			0
toilet same BRS L4 443 (automatic adj5 flush\$3)	toilet same (automatic adj flush\$3)	toilet same 43 (automatic adj flush\$3)	adj		USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/25 14:45			0
BRS L5 156 L4 and sensor	5 156 L4 and senso	56 L4 and senso	and senso		USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/25			0
BRS L6 16 board)	6 16 L5 and (circuit nea	6 L5 and (circuit nea board)	(circuit nea		USPAT; US-PGPUB;2004/ EPO; JPO;14:46 DERWENT	2004/10/25 14:46			0
BRS L7 18 L4 and (rotat\$4 near!	18 L4 and (rotat\$4 near lever)	8 L4 and (rotat\$4 near lever)	(rotat\$4 near	5	USPAT; US-PGPUB; EPO; JPO; DERWENT	JB; 2004/10/25 20; 14:48			0